



PRODUCTION INSTRUCTION OF PO - 1929 / AO-AOR-16 / BOW (BM-25091)

DESCRIPTION	20*30
Party Quality	1500
Party Weight	0.581
Production Quality	1550
Production Weight	0.6
Pile Height - A	
Pile Height - B	
Pile Height - C	
Stitching 10 Cm A	
Stitching 10 Cm B	
Stitching 10 Cm C	
Width in Line 5 cms	
Middle Gape / Weaving Com	
1. Yarn UV/Non UV	
2. Canvas UV/Non UV	CANVAS 64 .600 GSM N
3. Canvas Size	20*30
4. Canvas Quality	
5. Canvas Weight @ PC.	0
6. Canvas Cutting Size	
7. Pipen Tanki Fold	
8. Stiching in 5 CMS	
9. Pipen Folder MM	
10. Latex	
11. Export Packing	

12. Carving	
TUMBLER / WASHING	
PC DYEING WEIGHT	
PC WASHING WEIGHT	
TUMBLING WEIGHT	.528
TUFFTING FINAL WEIGHT	
EXTRA WORK WEIGHT	
ORDER QUANTITY	1200