



PRODUCTION INSTRUCTION OF PO - 1912 / AO-AOG-7 / FLEURISTE-61127

DESCRIPTION	50*80	40*60
Party Quality	1600	1600
Party Weight	0.64	0.64
Production Quality	1649	1649
Production Weight	0.66	0.66
Pile Height - A		
Pile Height - B		
Pile Height - C		
Stitching 10 Cm A		
Stitching 10 Cm B		
Stitching 10 Cm C		
Width in Line 5 cms		
Niddle Gape / Weaving Com		
1. Yarn UV/Non UV		
2. Canvas UV/Non UV	CANVAS 64 .600 GSM N	CANVAS 64 .600 GSM N
3. Canvas Size	50*80	50*80
4. Canvas Quality		
5. Canvas Weight @ PC.	0	0
6. Canvas Cutting Size		
7. Pipen Tanki Fold		
8. Stiching in 5 CMS		
9. Pipen Folder MM		
10. Latex		
11. Export Packing		

12. Carving		
TUMBLER / WASHING		
PC DYEING WEIGHT		
PC WASHING WEIGHT		
TUMBLING WEIGHT	.640	.383
TUFFTING FINAL WEIGHT		
EXTRA WORK WEIGHT		
ORDER QUANTITY	1080	1080