



PRODUCTION INSTRUCTION OF PO - 2080 / AO-I T-66 / PLANE (SIP-022) 26-27

DESCRIPTION	60*60	60*90	60*90.
Party Quality	1800	1800	1800
Party Weight	.504	0.972	1.080
Production Quality	1984	1984	1984
Production Weight	.560	1.072	1.180
Pile Height - A	0	0	0
Pile Height - B	0	0	0
Pile Height - C	0	0	0
Stitching 10 Cm A	0	0	0
Stitching 10 Cm B	0	0	0
Stitching 10 Cm C	0	0	0
Width in Line 5 cms	0	0	0
Middle Gape / Weaving Com	CAM GAPE	CAM GAPE	CAM GAPE
1. Yarn UV/Non UV	UVC	UVC	UVC
2. Canvas UV/Non UV	CANVAS 53 .600 GSM	CANVAS 53 .600 GSM	CANVAS 53 .600 GSM
3. Canvas Size	53 INCH	53 INCH	53 INCH
4. Canvas Quality	.600 GSM	.600 GSM	.600 GSM
5. Canvas Weight @ PC.	.268	.402	.402
6. Canvas Cutting Size	63*66	63*99	63*90
7. Piben Tanki Fold	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
8. Stiching in 5 CMS	8-9	8-9	8-9
9. Piben Folder MM	AS PER SAMPLE	AS PER SAMPLE	AS PER SAMPLE
10. Latex	YES	YES	YES
11. Export Packing	NO	NO	NO

12. Carving	NO	NO	NO
TUMBLER / WASHING	NO	NO	NO
PC DYEING WEIGHT	.550	1.060	1.170
PC WASHING WEIGHT	0	0	0
TUMBLING WEIGHT	0	0	0
TUFFTING FINAL WEIGHT	.540-.560	1.050-1.070	1.160-1.180
EXTRA WORK WEIGHT	0	0	0
ORDER QUANTITY	100	1000	1000